



TIME SHEET

Start	5:28
Lunch	30
End	16:35
Reg hours	8
OT Hours	0.62
Tickets	15
Total Miles	81

Is MOB more than 50 miles? (Y/N)	N
Is DEMOB more than 50 miles? (Y/N)	N
MOB from? (Home/Hotel)	Home
DEMOB to? (Home/Hotel)	Home
MOB time	92
DEMOB time	64
Tolls paid? (Y/N)	N
MOB mileage	3080
DEMOB Mileage	3161

Name:	Lionel Andrade
Lan ID:	L2AZ
Date:	11/25/2025
Division:	De Anza
PG&E Supervisor:	Michael Hall
Supervisor Lan ID	MGHD@PGE.COM

Index	USA Ticket Number	Non Productive Time	Start Time	End Time	Total Min.	Status Gas	Status Electric	PM Number	Comments
1	MOB	92	5:28	7:00					Travel From Home
2	2025112102098		7:00	7:41	41	No Conflict	No Conflict	42910646	10144 Congress PI No conflict. Closed ticket. I also attended the DeAnza morning huddle during this ticket.
3	2025112101962		7:41	7:55	14	No Conflict	No Conflict	42910646	10080 United PI No conflict. Closed ticket.
4	2025112101871		7:55	7:56	1	No Conflict	No Conflict	42910646	21113 Stevens Creek Blvd No conflict. Closed ticket.
5	2025112101671		7:56	8:20	24	No Conflict	Facilities Marked	42910646	21111 Stevens Creek Blvd I located and marked (1)electric secondary line (1)electric primary line No PG&E gas within the delineated area or within the tolerance zone. Closed ticket.
6	2025110601110		8:20	10:09	109	Facilities Marked	Facilities Marked	42910646	21251 Stevens Creek Blvd I located and marked (1)1"PI gas service stub (1)6"Stl gas main line (1)electric secondary line I did also mark part of the 6"Stl gas main line using map measurements per PG&E DeAnza senior James #JD11 per the information provided by the PG&E as-builts. I also contacted the contractor to inform him of this as well. He said that is going to pothole to verify all facilities before excavation. Closed ticket.

7	2025112500729		10:09	10:47	38	No Conflict	Facilities Marked	31770609	821 Bubb Rd I located and marked (2)electric primary lines No PG&E gas within the delineated area or within the tolerance zone. Closed ticket.
8	2025090903397		10:47	10:53	6	No Remark Required	No Remark Required	35583030	No Re-Marks Required. Closed ticket.
9	2025112100210		10:53	11:12	19	Excavated Before Marked	Excavated Before Marked	42910646	10460 Bubb Rd Excavated before marked. I met with the contractor on site and he showed me the work area. All of their work is in the interior of the building. Closed ticket.
10	2025112101035		11:12	11:56	44	Facilities Marked	No Conflict	42910646	1016 Havre Ct I located and marked (1)3/4"Stl gas service line (1)2"Stl gas main line No PG&E electric within the delineated area or within the tolerance zone. Closed ticket.
11	2025112101729		11:56	12:35	39	No Conflict	No Conflict	42910646	1336 Bobolink Cir No conflict. Closed ticket.
12	2025112101738		12:35	12:36	1	No Conflict	No Conflict	42910646	1354 Bobolink Cir No conflict. Closed ticket.
13	Lunch	30	12:36	13:06					
14	2025112101716		13:06	13:25	19	No Conflict	No Conflict	42910646	630 Carlisle Way No conflict. Closed ticket.
15	2025112101681		13:25	13:28	3	No Conflict	No Conflict	42910646	644 Carlisle Way No conflict. Closed ticket. Also ticket #202511211698
16	2025112400030		13:28	14:07	39	No Conflict	Facilities Marked	42910646	21111 Stevens Creek Blvd I located and marked (1)electric secondary line (1)electric primary line No PG&E gas within the delineated area or within the tolerance zone. Closed ticket.
17	2025112400808		14:07	15:31	84	Facilities Marked	Facilities Marked	42910646	1790 W. Fremont Ave I located and marked (1)1/2"PI gas service line (1)3"PI gas main line (1)electric service line I attempted to locate a PG&E owned streetlight but I couldn't produce a signal and will meet with the senior on site to troubleshoot. Ongoing.
18	DEMOB	64	15:31	16:35					Travel To Home